SERVICE BULLETIN

SUBJECT: RATING OF SYNCHRO FUSE FOR ADF 2 (CUSTOMER OPTION G77) CHANGED FROM 0.5 AMP TO 1.0 AMP (MODIFICATION N287)

1. Planning Information

A. Effectivity

(1) Aircraft Affected

All Nomad N22-series and N24-series aircraft fitted with Customer Option G77 and which do not already embody Mod N287.

Pre-certification implementation of the intent of this service bulletin is recorded in the airframe log book as Mod N287.

(2) Spares Affected

None.

B. Reason

ADF 2 synchro fuse was underrated.

C. Description

The 0.5-amp fuse fitted in the ADF 2 position in the AC distribution box is changed to a 1.0-amp fuse.

D. Compliance

At next scheduled servicing after receipt of this service bulletin.

E. Approval

The modification detailed herein has been approved pursuant to Air Navigation Regulation 40 and conforms with the type certification requirements.

F. Manpower

One manhour.

G. Material - Price and Availability

Refer Para 3.A.

H. Tooling - Price and Availability

None required.

J. Weight and Balance

No effect.

K. References

Maintenance Manual (MM).

L. Publications Affected

Illustrated Parts Catalogue. Wiring Diagram Manual.

2. Accomplishment Instructions

CAUTION: ENSURE ALL ELECTRICAL POWER IS DISCONNECTED.

Remove and discard the 0.5-amp fuse fitted in the ADF 2 SYNCHROS position on the AC distribution box (Ref MM, Option G77 Supplement, Figure 1) and replace with a 1.0-amp fuse P/N F02A250-1A.

3. Materials Information

A. Parts Required per Aircraft:

The operator is required to provide the following item from stock or local sources:

<u>Item P/N</u> <u>Title</u> <u>Qty</u> F02A250-1A Fuse, 1.0-amp 1

B. Parts Modified and Re-identified by the Operator

None.

C. Parts Required to Modify Spares

None.

D. Removed Parts

Item P/N	<u>Title</u>	Qty	Recommended Disposition
F02A250-1/2A	Fuse, 0.5-amp	1	Scran

E. Special Tools and Equipment Required

None.

4. Record compliance with Service Bulletin NMD-34-3 in the airframe log book.