Reference No. 202

#### TRANSMITTAL SHEET FOR NOMAD SERVICE BULLETIN

SERVICE BULLETIN NO: NMD-52-7

DATED: 9th February, 1990

TITLE:

Doors - Aft Passenger Door - Improved Mechanical Stop

(Modification N638)

**REVISION NO:** 

DATE:

ACTION: Insert Service Bulletin NMD-52-7 into Service Bulletin

publication and annotate index accordingly.

REASON: To strengthen the diaphram in the vicinity of the mechanical

stop.

**REMARKS:** 

G. Refit lower trim to the door.

## 3. MATERIAL INFORMATION

A. Parts required per aircraft.

New Part No	<u>Qty</u>	<u>Title</u>	Qld P/N	Disposition
1A/N-11-1377SB	1	Bracket		Note 2
1B/N-11-1377SB	1	Angle		Note 2
MS20470AD4-5	11	Rivet		
MS20600AD4W2	11	Rivet (Alt)		Note 1
MS20426AD3-5	2	Rivet		<del>-</del>

Note 1: CR 3213-4-2 is also an acceptable alternative Note 2: Made from 0.050 inch Al Alloy QQ-A-250/5 T3

## 4. SPECIAL TOOLS AND EQUIPMENT

None

## 5. RECORDING ACTION

Record compliance with Service Bulletin NMD-52-7 in Airframe Log Book.

## DOORS - AFT PASSENGER DOOR-IMPROVED MECHANICAL STOP (MODIFICATION N638)

#### 1. PLANNING INFORMATION

### A. Effectivity

All Nomad N22 Series and N24 Series aircraft whose log books do not record the embodiment of Mod N638 or compliance with Service Bulletin NMD-52-7.

Aircraft Serial No  $\,$  N22S-159 to N22S-165 inclusive have this modification incorporated as basic.

#### B. Reason

To strengthen the diaphram in the vicinity of the mechanical stop.

## C. <u>Description</u>

The under side of the diaphragm is strengthened by the addition of a re-inforcing bracket and angle.

## D. <u>Compliance</u>

Recommended.

#### E. Approval

The modification detailed herein has been approved pursuant to CAR 35 and conforms with type certification requirements.

### F. Manpower

Three manhours.

Page No	1	2	3	4	5	6
Rev No		-	-	-		-

#### G. <u>Material</u> - Price and Availability

Material to be obtained from ASTA. Price and availability on request.

#### H. Tooling

Nil required.

#### J. Weight and Balance

None

#### K. References

IPC - Illustrated Parts Catalogue 52-15-02.


### L. <u>Publications Affected</u>

Nil.


## 2. ACCOMPLISHMENT INSTRUCTIONS


- A. Remove the lower trim from the passenger door.
- B. Drill out the two rivets as shown in Figure 1 View on Arrow B. Inspect area around rivet holes for any signs of cracking. If the area is cracked, stop drill using a 1/8 in dia drill.
- C. Make a bracket 1A/N-11-1377SB and angle 1B/N-11-1377SB as shown in Figs 2 and 3 respectively.
- D. Position the bracket and angle and, using the bracket and angle as templates, drill rivet holes in the diaphram and door frame with a #30 drill. Using a  $\oint$  2.45 mm drill, drill out two rivets from the outer skin to match the bracket as shown in Figure 1. Deburr all holes.
- E. Rivet bracket and angle to diaphram using MS20470AD4-5 rivets. Rivet bracket to outer skin using MS20426AD3-5 rivets and angle to door frame using MS20470AD4-5 rivets.
- F. Clean all swarf from inside door. Alodine and epoxy prime any bare metal.

NMD-52-7




Re-Inforcing of Aft Passenger Door Figure 1






PART NUMBER IA/N-II-1377 SB

Bracket Manufacturing Details Figure 2





MATERIAL 0.05 AL ALLOY QQ-A-250-5 T3

PART NUMBER 1B/N-11-1377SB

Angle Manufacturing Details Figure 3

NMD-52-

NMD-52-7