Reference No 233

# TRANSMITTAL LETTER FOR SERVICE BULLETIN NMD-55-29

#### STABILISERS — HORIZONTAL STABILISER — PIVOT BRACKET BUSH REWORK

#### Reason

1. The pivot bolt PN 2/N-00-44 has a machined radius between the bolt shank and the bolt head, which may interfere with pivot bracket PN 1/N-30-127.

#### Instructions

- 2. Insert the attached Service Bulletin NMD-55-29, dated 14 Jun 91 into the Service Bulletin binder. Annotate the Service Bulletin Index accordingly.
- 3. Remove the Service Bulletin Index dated 28 Nov 90 and insert the attached Service Bulletin Index dated 14 Jun 91.

#### **Revision Status**

Original

14 Jun 91

#### STABILISERS — HORIZONTAL STABILISER — PIVOT BRACKET BUSH REWORK

#### 1. PLANNING INFORMATION

#### A. Effectivity

All Nomad N22 Series and N24 Series aircraft whose log books do not already record the embodiment of Mod N663.

#### B. Reason

The Pivot Bolt PN 2/N-00-44 has a machined radius between the bolt shank and the bolt head which may interfere with Pivot Bracket PN 1/N-30-127.

#### C. Description

- (1) The internal faces of Pivot Bracket Bush PN 1/N-30-128 are to be inspected and, if necessary, pressed flush with the lugs of Pivot Bracket PN 1/N-30-127.
- (2) The external faces of Bush PN 1/N-30-128 are to be chamfered to allow the bolt head to seat properly.

#### D. Compliance

This Service Bulletin is to be carried out as follows:

- (1) when the horizontal stabiliser is next removed,
- (2) when new bushes are fitted to the horizontal stabiliser, and
- (3) to spare horizontal stabilisers and pivot brackets before installation on aircraft.

#### E. Approval

The rework detailed in this Service Bulletin has been approved pursuant to CAR 35 and conforms to type certification requirements.

#### F. Manpower

One manhour.

#### G. Material — Price and Availability

None required.

#### H. Tooling — Price and Availability

None required.

#### I. Weight and Balance

None.

Page No	1	2	3
Rev No	0	0	0

#### J. References

None.

#### K. Publications Affected

Maintenance Manual

#### 2. ACCOMPLISHMENT INSTRUCTIONS

- A. Inspect Bushes PN 1/N-30-128 to determine whether the internal faces are flush with the internal faces of Pivot Bracket PN 1/N-30-127 (Ref Fig 1). If bushes are flush, proceed to step B. If not, proceed as follows:
  - (1) Assemble Pivot Bolt PN 2/N-00-44, a sleeve of suitable length and diameter slightly less than that of the bush and a large flat washer to the pivot bracket as shown in Figure 2.
  - (2) Slowly tighten nut until the internal faces of the bush and lug are flush.
  - (3) Repeat for remaining bushes as required.
- B. Use a 90° angle countersink tool or countersink mini-grinder in a suitable hand tool to remove up to 0.030/0.035 in of material in accordance with Figure 1.
- C. Coat the worked area using CAD brush plating or pigmented varnish to prevent corrosion.
- D. Identify the reworked bush by applying a small dot of red lacquer on external faces of bush.

#### 3. MATERIALS INFORMATION

None Required.

#### 4. RECORDING ACTION

Record compliance with Service Bulletin NMD-55-29 in the Airframe Log Book. Ensure horizontal stabiliser serial number is also recorded.




Figure 1 Horizontal Stabiliser Attachment Brackets - Modification to Bushes




Figure 2 Method For Pressing Bushes Flush With Pivot Bracket