

SL-GA8-2012-13 Issue 1

PO Box 881, Morwell, Victoria 3840, Australia Ph + 61 (0) 3 5172 1200 Fax + 61 (0) 3 5172 1201 www.gippsaero.com

# **Service Letter**

# Subject:

Replacement Vacuum Switch

# Applicability:

All GA8 aircraft fitted with vacuum switch P/N GA8-372011-011.

#### Amendments:

Nil (initial issue).

# **Background:**

Unsatisfactory reliability of the original Vacuum system warning switch has required the introduction of a new switch P/N GA8-372012-011, which supersedes switch P/N GA8-372011-011. The GA8-372011-011 switch remains "On Condition" and need only be replaced with the new switch on failure. The GA8 IPC will be revised to reflect this change.

## Instructions:

Prior to replacing the original switch, refer to Section **31-10-10** of the GA8 Service Manual for more instructions about Flight Instruments Sub Panel removal/installation. Furthermore, refer to Section **24-10-00** for Schematics.

#### Note

This vacuum switch has been set to close with an applied vacuum pressure of 2.75 inches of Hg +/- 0.25. This is 1 inch Hg lower than the original switch.

Carry out following procedure for Vacuum Switch replacement:

- 1. Remove Flight Instruments Sub Panel.
- 2. Remove the original switch from the flight instrument panel.
- 3. Install the switch as shown in Figures 1 and 2.
- 4. Fit a cable tie over the hose joined to the inlet of the switch. Pull tight. Cut off the cable tie end cleanly ensuring that no sharp edge is present.
- 5. Connect circuits WV1B22 and WV1C22N to the terminals of the vacuum switch assembly. The switch is not polarised.
- 6. Re-install Flight Instruments Sub Panel.

### Support

Should you require any further information please contact our Customer Support Department:

Tel.: +61 (0) 3 5172 1200

Fax.: +61 (0) 3 5172 1201

Email: support@gippsaero.com

SL-GA8-2012-13	Issue: 1	Date of Issue: 20.09.2012	Page 1 of 2
----------------	----------	---------------------------	-------------




Figure 1 Side view of the installed switch.



Figure 2. Completed installation.

NOTE:
The cable tie used around the short hose shown shall be firm, but not excessively tight so as to cause a restriction.

SL-GA8-2012-13	Issue: 1	Date of Issue: 20.09.2012	Page 2 of 2
----------------	----------	---------------------------	-------------