Reference No. 8

Nomad SERVICE BULLETIN

TIGHTNESS CHECK OF JUBILEE TYPE HOSE CLAMPS USED FUEL SYSTEM. SUBJECT IN FUEL LINES.

EFFECTIVITY NOMAD N22 Aircraft

Serial Nos. N22-1, N22-2, N22-4 and N22-5.

One instance has been reported whereby an incorrectly secured hose REASON joining two rigid fuel pipes has caused a fuel leak.

This bulletin requires access to be made to all fuel lines DESCRIPTION so that tightness of "Jubilee" type clamps used on hose connections between rigid pipes be checked.

To be carried out at next daily inspection. COMPLIANCE

Approximately 1 manhour is required to carry out these checks. MANPOWER

KIT COSTS Not Applicable.

WEIGHT AND BALANCE None.

Telex Y2850/601-2-7 of 13th August from P.D.S. Engineer G.A.F. REFERENCES Maintenance Manual Chapter 28.

PUBLICATIONS AFFECTED Nil.

Reference No. 8

Nomad SERVICE BULLETIN

TIGHTNESS CHECK OF JUBILEE TYPE HOSE CLAMPS USED FUEL SYSTEM. SUBJECT IN FUEL LINES.

EFFECTIVITY NOMAD N22 Aircraft

Serial Nos. N22-1, N22-2, N22-4 and N22-5.

One instance has been reported whereby an incorrectly secured hose REASON joining two rigid fuel pipes has caused a fuel leak.

This bulletin requires access to be made to all fuel lines DESCRIPTION so that tightness of "Jubilee" type clamps used on hose connections between rigid pipes be checked.

To be carried out at next daily inspection. COMPLIANCE

Approximately 1 manhour is required to carry out these checks. MANPOWER

KIT COSTS Not Applicable.

WEIGHT AND BALANCE None.

Telex Y2850/601-2-7 of 13th August from P.D.S. Engineer G.A.F. REFERENCES Maintenance Manual Chapter 28.

PUBLICATIONS AFFECTED Nil.