

Nomad

SERVICE LETTER

98-1

FLAP PIVOT PINS - CORROSION INSPECTION & TREATMENT

A. INSTRUCTIONS

1. Remove Service Letter 98-1 dated 14 September 1998 from the Service Letter binder and destroy.
2. Insert Service Letter 98-1 Revision 1 into the Service Letter binder. Annotate index accordingly.

B. INTRODUCTION

1. There have been reports of corrosion forming in the bores of the Flap Pivot Pins.

C. SCOPE

1. This Service Letter applies to all Nomad aircraft.

D. INSPECTION

1. Refer to the Corrosion Control Manual Section 7, Para H.

E. TREATMENT

1. Refer to the Corrosion Control Manual Section 7, Para H.

F. RECOMMENDATION

1. Incorporate this Service Letter at the next scheduled maintenance check after receipt.

VICTOR BIBBY
TECHNICAL SERVICES MANAGER

Original: Issued on 14 September 1998
Revision 1: To clarify correct procedures for inspection and treatment.