

Service Letter

Subject:

Flap and Aileron Arm Replacement.

Applicability:

All GA8 serial numbers.

Amendments:

Nil (initial issue).

Background:

SB-GA8-2009-57 documents the procedure for replacement of the flap and aileron drop arms on the GA8 Airvan. Arms may be replaced on an individual basis or as a complete set as required.

This Service Bulletin is to be incorporated by Gippsland Aeronautics personnel only.

Should you require any further information please contact our Product Support Department:

Tel.: +61 03 5172 1200

Fax.: +61 03 5172 1201

Email: support@gippsaero.com

Compliance:

For applicable aircraft the referenced optional Service Bulletin may be incorporated at the owner's discretion.