

Service Bulletin

Subject:

Longer Passenger Seat Harness

Applicability:

All GA8 passenger seats fitted with harness P/N 3026-1-011-2396. These harnesses have been installed in aircraft up to serial number GA8-05-085. Aircraft S/N's GA8-05-086 and subsequent have been fitted with the extended passenger seat harnesses in production.

Amendments:

Nil – Initial Issue.

Background:

In response to requests from operators for increased passenger seat belt length, a new Amsafe TSO'd 3 point harness featuring an additional 14" of webbing length has been introduced. This Service Bulletin details the fitting of the new harness into existing GA8 aircraft.

Compliance:

Compliance with this service bulletin is optional.

Weight and Balance:

Negligible effect.

Approval:

The technical aspects of this Service Bulletin have been approved under a CASA Authorisation.

Parts:

Item	P/N	Description	Qty
1	3026-1-021-2396	Amsafe 3 point harness	A/R

Parts Availability:

Parts can be obtained directly from Gippsland Aeronautics.

Tel.: +61 03 5172 1208

Fax.: +61 03 5172 1237

Email: spares@gippsaero.com

Labour:

Approximately 0.5 hours per seat should be allocated for completing the work detailed in this service bulletin.

Warranty:

Gippsland Aeronautics factory participation is limited to the supply of parts, including freight, at the owner's expense.

Instructions:**1. For each seat that the new harness is to be fitted:**

- 1.1. Remove the seat from the aircraft.
- 1.2. Remove the harness from the seat per section 25-20-02 of the GA8 Service Manual. If fitted discard the seat belt extender plates (3 off).
- 1.3. Installation of the new harness is the reverse of the above procedure.
- 1.4. Reinstall seat in aircraft.

Documentation:

Update aircraft log book to reflect incorporation of this Service Bulletin.

Compliance Notice:

Complete the Document Compliance Notice and return to Gippsland Aeronautics by mail, fax or email.

DOCUMENT COMPLIANCE NOTICE



Document: Service Bulletin SB-GA8-2005-28

Aircraft Serial Number: GA8-_____

Service Bulletin SB-GA8-2005-28 Issue 01 has been incorporated in the above aircraft.

Date: _____

Signed

Print Name: _____

Please post or fax this compliance notice to:

Gippsland Aeronautics
Attn: Technical Services
P.O. Box 881
Morwell Victoria 3840
Australia
Fax.: +61 03 5172 1201