

SL-GA8-2010-20 Issue 1

PO Box 881, Morwell, Victoria 3840, Australia Ph + 61 (0) 3 5172 1200 Fax + 61 (0) 3 5172 1201 www.gippsaero.com

Service Letter

Subject:

Crew Seat Rail Extension

Applicability:

Serial numbers GA8-00-004 through GA8-08-140.

Amendments:

Nil (initial issue).

Background:

Service Bulletin SB-GA8-2009-48 is available from Gippsland Aeronautics Customer Support for the modification of the affected aircraft to allow approximately 2.5 inches of additional legroom for the crew. Incorporation of this Service Bulletin requires significant structural modification and as such is limited to maintenance personnel approved by Gippsland Aeronautics.

Should you require any further information please contact our Customer Support Department:

Tel.: +61 03 5172 1200 Fax.: +61 03 5172 1201 Email: support@gippsaero.com

Compliance:

For applicable aircraft the referenced optional Service Bulletin may be incorporated at the owner's discretion.

SL-GA8-2010-19	Issue: 1	Date of Issue: 25 Jan 2010	Page 1 of 1
----------------	----------	----------------------------	-------------